



Date: January 17th, 2020

Petronas Energy Canada Ltd
1600-215- 2nd Street SW
Calgary, AB T2P 1M4

Attention: Carl Lammens, Team Lead, Asset Retirement & Remediation

Re: Petronas Energy Canada Certificate of Restoration Application (Part-II) for the Well Site Petronas PC Altares B-84-A/94-B-08 (WA # 6318)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report (**Schedule B**) for wellsite for the above referenced well authorization (WA # 6318) submitted by Acden Vertex Limited Partnership on behalf of Petronas Energy Canada Ltd on December 23rd, 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 6069).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Petronas Energy Canada Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer
Resource Development & Stewardship Branch
Operational Policy & Environment
Telephone: 250-794-5234
Facsimile: 250-794-5390
E-Mail: Taher.Morsi@gov.bc.ca

cc: Steven vanNieuwkerk, Acden Vertex Limited Partnership, 161, 2055 Premier Way, Sherwood Park, AB T8H 0G2



**CERTIFICATION OF RESTORATION
APPLICATION FORM - PART 2**
 Physical Address: 6534 Airport Road,
 Fort St. John, B.C. V1J 4M6
 Mailing Address: Bag 2, Fort St. John, B.C.
 V1J 2B0
 Phone: (250) 794-5200

RECEIVED
 DEC 23 2019
 BC Oil and Gas Commission
 Peter Reppert
 Chief of Administration

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 47, and the Environmental Management Act S.B.C. 2009, c. 53, in conformity to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

Commission File No. or AD No.:		Document:	
Well Permit No.: 06318		ADMINISTRATION	
Well Name: PETRONAS PC ALTARES B-084-A094-B-08	Well Location: B-084-A094-B-08	A	
Petroleum Title (Permit, Lease, Number, etc): OGC File #: N/A		B	
Title Holder(s) (Permitter, Lessee, etc): PETRONAS Energy Canada Ltd.			
Surface Landowner: Crown	Surface Occupant: N/A		
<i>(Attach Letter of Release)</i>			
Applicant's Agent in Field			
Name: Steven vanNieuwerkerk			
Company: Accden Vertex Limited Partnership			
Position: General Manager, Report Review			
Address: 161, 2055 Premier Way		8810 81st Street, Spruce Grove, AB T9V 0T8	
Postal Code: T8H 0G2	Phone: 780-464-3285	Fax: 780-464-3731	Province: Alberta
Agent Signature: <i>Steve Van Nieuwerkerk</i>		Email: svannieuwerkerk@vertex.ca	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached		Date: December 18, 2019	
PAY TO THE ORDER OF THE BC OIL & GAS COMMISSION			
Description of Area(s) Restored (Location, Remedy Steps, Pesticides and other disturbed areas affiliated with this location):			
Wellsite and access road.			
Details of any areas left untreated at Landowner's request:			
N/A			
Was 'Approval to Construct' subject to any reclamation conditions?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Reclamation Inspection Report Included?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B			
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			

CERTIFICATE OF RESTORATION

CERTIFICATE NO. 6069

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jan 17, 2020



Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.